Digital Surrogate of NARA Original Record - NND 927605

USS X-1 (SS X-1) ZONE DESCRIPTION ______ DATE Friday 1 June, 1956
(Day) (Date) (Month)

AT/~~PASSAGE FROM~~ Portsmouth Naval Shipyard to Portsmouth New Hampshire

WEATHER OBSERVATIONS

ZONE TIME	WIND DIRECTION (True)	WIND FORCE (Knots)	VISIBILITY (Miles)	WEATHER (Symbols)	BAROMETER (Inches)	TEMPERATURE Dry Bulb	TEMPERATURE Wet Bulb	CLOUDS Amount (Tenths)	CLOUDS Height	CLOUDS Type	SEA WATER TEMPERATURE	WAVES DIRECTION (True)	WAVES HEIGHT (Feet)
04													
08													
12	Same as Com Nav Base												
16													
20	Portsmouth New Hampshire												
24													

POSITION	ZONE	TIME
0800 L ______ BY ______		
λ ______ BY ______		
1200 L ______ BY ______		
λ ______ BY ______		
2000 L ______ BY ______		
λ ______ BY ______		

LEGEND: 1—CELESTIAL 2—ELECTRONIC 3—VISUAL 4—D. R.

REMARKS

0000-2400 Resting on cradles in front of building 180, at Portsmouth Naval Shipyard, Portsmouth New Hampshire. Receiving all power from shore. SOPA is Commanding officer of U.S.S. Piper (SS409). 0800 Mustered crew at quarters, no unauthorized absentees

Phillip S Thompson
EN1 (SS) USN

APPROVED: Kevin Hanson LT U. S. N. COMMANDING

EXAMINED: ______ U. S. N. NAVIGATOR.
(SIGNATURE REQUIRED ONLY WHEN NAVIGATOR IS OTHER THAN COMMANDING OFFICER.)

Digital Surrogate of NARA Original Record - NND 927605

USS X-1 (SSX-1) ZONE DESCRIPTION +4 DATE SATURDAY 2 JUNE, 1956
(Day) (Date) (Month)

AT/PASSAGE FROM U.S. NAVAL SHIPYARD, PORTSMOUTH, NEW HAMPSHIRE,

WEATHER OBSERVATIONS

ZONE TIME	WIND		VISIBILITY	WEATHER	BAROMETER	TEMPERATURE		CLOUDS			SEA WATER TEMPERATURE	WAVES	
	DIRECTION (True)	FORCE (Knots)	(Miles)	(Symbols)	(Inches)	Dry Bulb	Wet Bulb	Amount (Tenths)	Height	Type		DIRECTION (True)	HEIGHT (Feet)
04													
08													
12	SAME AS COM NAV BASE, PORTSMOUTH, N.H.												
16													
20													
24													

POSITION	ZONE	TIME
0800		
L		BY
λ		BY
1200		
L		BY
λ		BY
2000		
L		BY
λ		BY

LEGEND: 1—CELESTIAL 2—ELECTRONIC 3—VISUAL 4—D. R.

REMARKS

0000-2400 Resting on cradle in front of Building 180 at the U.S. Naval Shipyard Portsmouth, New Hampshire. Recieving all power from shore. S.O.P.A. Commanding Officer of the U.S.S. Albacore (AGSS-569). 0800 mustered crew at quarters. No unauthorized absentees.

Emmett M. Partain
EM1(SS) U.S.N.

APPROVED: Kevin Hanson U. S. N. COMMANDING

EXAMINED: ______ U. S. N. NAVIGATOR.
(SIGNATURE REQUIRED ONLY WHEN NAVIGATOR IS OTHER THAN COMMANDING OFFICER.)

Digital Surrogate of NARA Original Record - NND 927605

USS X-1 (SSX-1) ZONE DESCRIPTION +4 DATE Sunday (Day) 3 (Date) June (Month), 1956

AT/PASSAGE FROM U.S. Naval Shipyard TO Portsmouth New Hampshire

WEATHER OBSERVATIONS

ZONE TIME	WIND DIRECTION (True)	WIND FORCE (Knots)	VISIBILITY (Miles)	WEATHER (Symbols)	BAROMETER (Inches)	TEMPERATURE Dry Bulb	TEMPERATURE Wet Bulb	CLOUDS Amount (Tenths)	CLOUDS Height	CLOUDS Type	SEA WATER TEMPERATURE	WAVES DIRECTION (True)	WAVES HEIGHT (Feet)
04													
08													
12	Same as Com Nav Base, Portsmouth N.H.												
16													
20													
24													

POSITION	ZONE	TIME
0800		
L		BY
λ		BY
1200		
L		BY
λ		BY
2000		
L		BY
λ		BY

LEGEND: 1—CELESTIAL 2—ELECTRONIC 3—VISUAL 4—D. R.

REMARKS

0000-2400 Resting on cradles in front of building 180 at U.S. Naval Shipyard, Portsmouth New Hampshire, Receiving all power from shore. SOPA is Commanding officer of U.S.S. albacore (AGSS-569) 0800 mustered crew at quarters, no unauthorized absentees. 1200 commenced battery charge. 1700 secured battery charge

Phillip S Thompson
EN1(SS) USN

APPROVED: Kevin Hanlon U. S. N. COMMANDING
LT

EXAMINED: ______ U. S. N. NAVIGATOR.
(SIGNATURE REQUIRED ONLY WHEN NAVIGATOR IS OTHER THAN COMMANDING OFFICER.)

Digital Surrogate of NARA Original Record - NND 927605

Jim

USS X-1 (SSX-1) ZONE DESCRIPTION ______ DATE Monday (Day) 4 (Date) June (Month), 1956

AT/~~PASSAGE~~ FROM U.S. NAVAL SHIPYARD, PORTSMOUTH, NEW HAMPSHIRE TO

WEATHER OBSERVATIONS

ZONE TIME	WIND		VISIBILITY	WEATHER	BAROMETER	TEMPERATURE		CLOUDS			SEA WATER TEMPERATURE	WAVES	
	DIRECTION (True)	FORCE (Knots)	(Miles)	(Symbols)	(Inches)	Dry Bulb	Wet Bulb	Amount (Tenths)	Height	Type		DIRECTION (True)	HEIGHT (Feet)
04													
08													
12	SAME AS COM NAV BASE. PORTSMOUTH N.H.												
16													
20													
24													

POSITION	ZONE	TIME
0800		
L ______		BY ______
λ ______		BY ______
1200		
L ______		BY ______
λ ______		BY ______
2000		
L ______		BY ______
λ ______		BY ______

LEGEND: 1—CELESTIAL 2—ELECTRONIC 3—VISUAL 4—D. R.

REMARKS

0000-2400 RESTING ON CRADLES IN FRONT OF BUILDING 180 AT PORTSMOUTH NAVAL SHIP YARD, PORTSMOUTH, NEW HAMPSHIRE RECEIVING ALL POWER FROM SHORE. SOPA IS COMMANDING OFFICER U.S.S. ALBACORE (AGSS 569). 0800 MUSTERED CREW AT QUARTERS NO UNAUTHORIZED ABSENTEES.

James L. Flaherty

ET2(SS) USN.

APPROVED: Kevin Hanson LT U.S.N. COMMANDING

EXAMINED: ______ U.S.N. NAVIGATOR.

(SIGNATURE REQUIRED ONLY WHEN NAVIGATOR IS OTHER THAN COMMANDING OFFICER.)

348603 O - 55 - 3

Digital Surrogate of NARA Original Record - NND 927605

USS X-1 (SSX-1) ZONE DESCRIPTION +4 DATE Tuesday (Day) 5 (Date) June (Month), 1956

AT/PASSAGE FROM U. S. Naval Shipyard, TO Portsmouth, New Hampshire.

WEATHER OBSERVATIONS

ZONE TIME	WIND DIRECTION (True)	WIND FORCE (Knots)	VISIBILITY (Miles)	WEATHER (Symbols)	BAROMETER (Inches)	TEMPERATURE Dry Bulb	TEMPERATURE Wet Bulb	CLOUDS Amount (Tenths)	CLOUDS Height	CLOUDS Type	SEA WATER TEMPERATURE	WAVES DIRECTION (True)	WAVES HEIGHT (Feet)
04													
08													
12					SAME AS COMNAVBASE,								
16					PORTSMOUTH, N.H.								
20													
24													

POSITION	ZONE	TIME
0800		
L		BY
λ		BY
1200		
L		BY
λ		BY
2000		
L		BY
λ		BY

LEGEND: 1—CELESTIAL 2—ELECTRONIC 3—VISUAL 4—D. R.

REMARKS

0000-2400 Resting on cradle in front of Building 180 at the U. S. Naval Shipyard, Portsmouth, New Hampshire. Recieving all power from shore. S. O. P. A. Commanding Officer of the U. S. S. Piper (SS-409). 0800 mustered crew at quarters. No unauthorized absentees

Emmett M. Partain
EM1(SS) U. S. N.

APPROVED: Kevin Hanlon U. S. N. COMMANDING
LT

EXAMINED: _______ U. S. N. NAVIGATOR.

(SIGNATURE REQUIRED ONLY WHEN NAVIGATOR IS OTHER THAN COMMANDING OFFICER.)

Digital Surrogate of NARA Original Record - NND 927605

USS X-1 (SSX-1) ZONE DESCRIPTION +4 DATE WEDNESDAY (Day) 6 (Date) JUNE (Month), 1956

AT/~~PASSAGE~~ FROM US NAVAL SHIPYARD PORTSMOUTH NEW HAMPSHIRE

WEATHER OBSERVATIONS

ZONE TIME	WIND		VISIBILITY	WEATHER	BAROMETER	TEMPERATURE		CLOUDS			SEA WATER TEMPERATURE	WAVES	
	DIRECTION (True)	FORCE (Knots)	(Miles)	(Symbols)	(Inches)	Dry Bulb	Wet Bulb	Amount (Tenths)	Height	Type		DIRECTION (True)	HEIGHT (Feet)
04													
08													
12			SAME AS COM NAV BASE										
16			PORTSMOUTH NEW HAMPSHIRE.										
20													
24													

POSITION	ZONE	TIME
0800		
L		BY
λ		BY
1200		
L		BY
λ		BY
2000		
L		BY
λ		BY

LEGEND: 1—CELESTIAL 2—ELECTRONIC 3—VISUAL 4—D. R.

REMARKS

0000-2400 Resting on cradle in front of Building 180 at the US Naval shipyard Portsmouth New Hampshire Recieving all power from shore. SOPA is Commanding Officer of the USS Piper (SS409) 0800 Mustered crew at quarters, no unauthorized absentees

Charles W. Annath
EN2(SS) USN.

APPROVED: Kevin Hanlon U. S. N. COMMANDING
LT

EXAMINED: ______ U. S. N. NAVIGATOR.
(SIGNATURE REQUIRED ONLY WHEN NAVIGATOR IS OTHER THAN COMMANDING OFFICER.)

348603 O - 55 - 3

Digital Surrogate of NARA Original Record - NND 927605

USS X-1 (SSX-1) ZONE DESCRIPTION +4 DATE Thursday (Day) 7 (Date) June (Month), 1956

AT/~~PASSAGE FROM~~ U.S. Naval Shipyard Portsmouth TO New Hampshire

WEATHER OBSERVATIONS

ZONE TIME	WIND DIRECTION (True)	WIND FORCE (Knots)	VISIBILITY (Miles)	WEATHER (Symbols)	BAROMETER (Inches)	TEMPERATURE Dry Bulb	TEMPERATURE Wet Bulb	CLOUDS Amount (Tenths)	CLOUDS Height	CLOUDS Type	SEA WATER TEMPERATURE	WAVES DIRECTION (True)	WAVES HEIGHT (Feet)
04													
08													
12													
16													
20													
24													

Same as ComNavBase Portsmouth New Hampshire

POSITION	ZONE	TIME
0800 L		BY
λ		BY
1200 L		BY
λ		BY
2000 L		BY
λ		BY

LEGEND: 1—CELESTIAL 2—ELECTRONIC 3—VISUAL 4—D. R.

REMARKS

0000-2400 Resting on cradles in front of building 180 at the U.S. Naval Shipyard Portsmouth New Hampshire, Receiving all power from shore. SOPA is Commanding officer of the U.S.S. Piper (SS409). 0800 Mustered crew at quarters, no unauthorized absentees

Malone A. Jones
ENC(SS) USN

APPROVED: Kevin Hanlon LT U. S. N. COMMANDING

EXAMINED: ______ U. S. N. NAVIGATOR.
(SIGNATURE REQUIRED ONLY WHEN NAVIGATOR IS OTHER THAN COMMANDING OFFICER.)

Digital Surrogate of NARA Original Record - NND 927605

USS X-1 (SSX-1) ZONE DESCRIPTION +4 DATE Friday (Day) 8 (Date) June (Month), 1953

AT/PASSAGE FROM U S Naval Shipyard, TO Portsmouth, N. H.

WEATHER OBSERVATIONS

ZONE TIME	WIND		VISIBILITY	WEATHER	BAROMETER	TEMPERATURE		CLOUDS			SEA WATER TEMPERATURE	WAVES	
	DIRECTION (True)	FORCE (Knots)	(Miles)	(Symbols)	(Inches)	Dry Bulb	Wet Bulb	Amount (Tenths)	Height	Type		DIRECTION (True)	HEIGHT (Feet)
04													
08													
12		Same As ComNavBase											
16													
20		Portsmouth, New Hampshire											
24													

POSITION	ZONE	TIME
0800		
L		BY
λ		BY
1200		
L		BY
λ		BY
2000		
L		BY
λ		BY

LEGEND: 1—CELESTIAL 2—ELECTRONIC 3—VISUAL 4—D. R.

REMARKS

0000-2400 Resting on cradles in front of building 180, U S Naval Shipyard, Portsmouth N. H. Receiving all power from shore. SOPA is Commanding Officer, USS Piper (SS409). 0800 Mustered crew at quarters, No unauthorized absentees. 1100 SOPA is Commanding officer, USS Albacore (SS569).

J. A. Robert
EM1 USN

APPROVED: Kevin Hanlon U. S. N. COMMANDING
LT

EXAMINED: ______ U. S. N. NAVIGATOR.
(SIGNATURE REQUIRED ONLY WHEN NAVIGATOR IS OTHER THAN COMMANDING OFFICER.)

Digital Surrogate of NARA Original Record - NND 927605

USS X-1 (SSX-1) ZONE DESCRIPTION +4 DATE SATURDAY (Day) 9 (Date) JUNE (Month), 1956

AT/PASSAGE FROM US NAVAL SHIPYARD PORTSMOUTH TO NEW HAMPSHIRE

WEATHER OBSERVATIONS

ZONE TIME	WIND		VISIBILITY	WEATHER	BAROMETER	TEMPERATURE		CLOUDS			SEA WATER TEMPERATURE	WAVES	
	DIRECTION (True)	FORCE (Knots)	(Miles)	(Symbols)	(Inches)	Dry Bulb	Wet Bulb	Amount (Tenths)	Height	Type		DIRECTION (True)	HEIGHT (Feet)
04													
08													
12			SAME AS COMNAVBASE										
16			PORTSMOUTH, NEW HAMPSHIRE										
20													
24													

POSITION	ZONE	TIME
0800 L	BY	
λ	BY	
1200 L	BY	
λ	BY	
2000 L	BY	
λ	BY	

LEGEND: 1—CELESTIAL 2—ELECTRONIC 3—VISUAL 4—D. R.

REMARKS

0000-2400 Resting on cradles in front of Building 180 at the US Naval Shipyard, Portsmouth New Hampshire. Receiving all Power from shore. SOPA is Commanding Officer USS Albacore SS(569) 0800 Mustered crew at quarters, no unauthorized absentees.

Charles W. Annatt
EN2(SS) USN

APPROVED: Kevin Hanlon U. S. N. COMMANDING
LT

EXAMINED: ______ U. S. N. NAVIGATOR.
(SIGNATURE REQUIRED ONLY WHEN NAVIGATOR IS OTHER THAN COMMANDING OFFICER.)

Digital Surrogate of NARA Original Record - NND 927605

USS X-1 (SSX-1) ZONE DESCRIPTION +4 DATE SUNDAY (Day) 10 (Date) JUNE (Month), 19 56

AT/PASSAGE FROM U.S. Naval Shipyard TO Portsmouth, N.H.

WEATHER OBSERVATIONS

ZONE TIME	WIND		VISIBILITY	WEATHER	BAROMETER	TEMPERATURE		CLOUDS			SEA WATER TEMPERATURE	WAVES	
	DIRECTION (True)	FORCE (Knots)	(Miles)	(Symbols)	(Inches)	Dry Bulb	Wet Bulb	Amount (Tenths)	Height	Type		DIRECTION (True)	HEIGHT (Feet)
04													
08													
12	Same as ComNavBase,												
16	Portsmouth, New Hampshire												
20													
24													

POSITION	ZONE	TIME
0800		
L		BY
λ		BY
1200		
L		BY
λ		BY
2000		
L		BY
λ		BY

LEGEND: 1—CELESTIAL 2—ELECTRONIC 3—VISUAL 4—D. R.

REMARKS

00-24 Resting on cradles in front of building 180, U.S. Naval Shipyard, Portsmouth, N.H. Receiving all power from shore. SOPA is commanding officer, USS Albacore (SS569) 0800 Mustered crew at quarters, no unauthorized absentees.

J. A. Roberts
EMI (SS) USN.

APPROVED: Kevin Hanlon U. S. N. LT COMMANDING

EXAMINED: U. S. N. NAVIGATOR.

(SIGNATURE REQUIRED ONLY WHEN NAVIGATOR IS OTHER THAN COMMANDING OFFICER.)

Digital Surrogate of NARA Original Record - NND 927605

USS X-1 (SSX-1) ZONE DESCRIPTION +4 DATE Monday (Day) 11 (Date) June (Month), 1956

AT/PASSAGE FROM U.S. Naval Shipyard TO Portsmouth New Hampshire

WEATHER OBSERVATIONS

ZONE TIME	WIND		VISIBILITY	WEATHER	BAROMETER	TEMPERATURE		CLOUDS			SEA WATER TEMPERATURE	WAVES	
	DIRECTION (True)	FORCE (Knots)	(Miles)	(Symbols)	(Inches)	Dry Bulb	Wet Bulb	Amount (Tenths)	Height	Type		DIRECTION (True)	HEIGHT (Feet)
04													
08													
12	Same as Com Nav Base												
16	Portsmouth New Hampshire												
20													
24													

POSITION	ZONE	TIME
0800		
L	BY	
λ	BY	
1200		
L	BY	
λ	BY	
2000		
L	BY	
λ	BY	

LEGEND: 1—CELESTIAL 2—ELECTRONIC 3—VISUAL 4—D. R.

REMARKS

0000-2400 Resting on cradles outside of building 180 at U.S. Naval Shipyard, Portsmouth New Hampshire. Receiving all power from shore. S.O.P.A is Commanding Officer U.SS Sea Robin (SS 407), 0800 Mustered crew at quarters, no unauthorized absentees. 0930 SOPA is Commanding Officer U.SS Piper (SS409)

Phillip S Thompson
EN1 (SS) USN

APPROVED:

Kevin Hanlon LT U. S. N. COMMANDING

EXAMINED:

_______________ U. S. N. NAVIGATOR.
(SIGNATURE REQUIRED ONLY WHEN NAVIGATOR IS OTHER THAN COMMANDING OFFICER.)

Digital Surrogate of NARA Original Record - NND 927605

USS X-1 (SSX-1) ZONE DESCRIPTION +4 DATE TUESDAY (Day) 12 (Date) JUNE (Month), 1956

AT/~~PASSAGE FROM~~ US NAVAL SHIPYARD, PORTSMOUTH NEW HAMPSHIRE

WEATHER OBSERVATIONS

ZONE TIME	WIND		VISIBILITY	WEATHER	BAROMETER	TEMPERATURE		CLOUDS			SEA WATER TEMPERATURE	WAVES	
	DIRECTION (True)	FORCE (Knots)	(Miles)	(Symbols)	(Inches)	Dry Bulb	Wet Bulb	Amount (Tenths)	Height	Type		DIRECTION (True)	HEIGHT (Feet)
04													
08													
12		SAME AS COM NAV BASE											
16		PORSTMOUTH, NEW HAMPSHIRE											
20													
24													

POSITION	ZONE	TIME
0800		
L		BY
λ		BY
1200		
L		BY
λ		BY
2000		
L		BY
λ		BY

LEGEND: 1—CELESTIAL 2—ELECTRONIC 3—VISUAL 4—D. R.

REMARKS

00-24 Resting on craddles outside of building 180 at US Naval Shipyard, Portsmouth New Hampshire, Recieving all power from shore, SOPA is C.O. USS Piper (SS409)
0800 Mustered crew at quarters, no unauthorized absentees.

Charles W. Annath
EN2(SS) USN.

APPROVED: Kevin Hanlon LT U. S. N. COMMANDING

EXAMINED: ______ U. S. N. NAVIGATOR.
(SIGNATURE REQUIRED ONLY WHEN NAVIGATOR IS OTHER THAN COMMANDING OFFICER.)

Digital Surrogate of NARA Original Record - NND 927605

USS X-1 (SSX-1) ZONE DESCRIPTION +4 DATE WEDNESDAY (Day) 13, (Date) JUNE (Month), 19 56

AT/~~PASSAGE~~ FROM PORTSMOUTH NAVAL SHIPYARD ~~TO~~ PORTSMOUTH N.H.

WEATHER OBSERVATIONS

ZONE TIME	WIND		VISIBILITY	WEATHER	BAROMETER	TEMPERATURE		CLOUDS			SEA WATER TEMPERATURE	WAVES	
	DIRECTION (True)	FORCE (Knots)	(Miles)	(Symbols)	(Inches)	Dry Bulb	Wet Bulb	Amount (Tenths)	Height	Type		DIRECTION (True)	HEIGHT (Feet)
04													
08													
12													
16													
20													
24													

SAME AS COMNAV BASE
PORTSMOUTH, NEW HAMPSHIRE

POSITION	ZONE	TIME
0800		
L		BY
λ		BY
1200		
L		BY
λ		BY
2000		
L		BY
λ		BY

LEGEND: 1—CELESTIAL
2—ELECTRONIC
3—VISUAL
4—D. R.

REMARKS

0000-2400 RESTING ON CRADLES IN FRONT OF BUILDING 180 AT PORTSMOUTH NAVAL SHIPYARD, PORTSMOUTH NEW HAMPSHIRE. RECEIVING ALL POWER FROM SHORE. SOPA IS COMMANDING OFFICER U.S.S. PIPER (SS409). 0800 MUSTERED CREW AT QUARTERS NO UNAUTHORIZED ABSENTEES.

James L. Flaherty
ET2(SS) USN.

APPROVED: Kevin Hanlon LT U. S. N. COMMANDING

EXAMINED: ________ U. S. N. NAVIGATOR.
(SIGNATURE REQUIRED ONLY WHEN NAVIGATOR IS OTHER THAN COMMANDING OFFICER.)

348603 O - 55 - 3

Digital Surrogate of NARA Original Record - NND 927605

USS X-1 (SSX-1) ZONE DESCRIPTION +4 DATE THURSDAY (Day) 14 (Date) JUNE (Month), 19 56

AT/PASSAGE FROM U.S. NAVAL SHIPYARD, PORTSMOUTH, NEW HAMPSHIRE

WEATHER OBSERVATIONS

ZONE TIME	WIND DIRECTION (True)	WIND FORCE (Knots)	VISIBILITY (Miles)	WEATHER (Symbols)	BAROMETER (Inches)	TEMPERATURE Dry Bulb	TEMPERATURE Wet Bulb	CLOUDS Amount (Tenths)	CLOUDS Height	CLOUDS Type	SEA WATER TEMPERATURE	WAVES DIRECTION (True)	WAVES HEIGHT (Feet)
04													
08													
12			SAME AS COM NAV BASE										
16			PORTSMOUTH, NEW HAMPSHIRE.										
20													
24													

POSITION	ZONE	TIME
0800 L		BY
λ		BY
1200 L		BY
λ		BY
2000 L		BY
λ		BY

LEGEND: 1—CELESTIAL 2—ELECTRONIC 3—VISUAL 4—D. R.

REMARKS

0000-2400 Resting on cradle in front of Building 180 at the U.S. Naval Shipyard, Portsmouth, New Hampshire. Receiving all power from shore. S.O.P.A. is Commanding Officer of the U.S.S. Piper (SS-409). 0800 Mustered crew at quarters. No unauthorized absentees.

Emmett M. Partain
EM1(SS) U.S.N.

APPROVED: Kevin Hanlon U. S. N. COMMANDING
LT

EXAMINED: ______ U. S. N. NAVIGATOR.
(SIGNATURE REQUIRED ONLY WHEN NAVIGATOR IS OTHER THAN COMMANDING OFFICER.)

Digital Surrogate of NARA Original Record - NND 927605

USS X-1 (SSX-1) ZONE DESCRIPTION +4 DATE FRIDAY (Day) 15 (Date) JUNE (Month), 1956

AT/~~PASSAGE~~ FROM U.S. NAVAL SHIPYARD, TO PORTSMOUTH, NEW HAMPSHIRE

WEATHER OBSERVATIONS

ZONE TIME	WIND		VISIBILITY	WEATHER	BAROMETER	TEMPERATURE		CLOUDS			SEA WATER TEMPERATURE	WAVES	
	DIRECTION (True)	FORCE (Knots)	(Miles)	(Symbols)	(Inches)	Dry Bulb	Wet Bulb	Amount (Tenths)	Height	Type		DIRECTION (True)	HEIGHT (Feet)
04													
08													
12					SAME AS COMNAVBASE								
16						PORTSMOUTH, NEW HAMPSHIRE							
20													
24													

POSITION	ZONE	TIME
0800		
L		BY
λ		BY
1200		
L		BY
λ		BY
2000		
L		BY
λ		BY

LEGEND: 1—CELESTIAL 2—ELECTRONIC 3—VISUAL 4—D. R.

REMARKS

0000-2400 RESTING ON CRADLES IN FRONT OF BUILDING 180 PORTSMOUTH NAVAL SHIPYARD, PORTSMOUTH NEW HAMPSHIRE. RECIEVING ALL POWER FROM SHORE. SOPA IS COMMANDING OFFICER V.S.S. PIPER (SS409). 0800 MUSTERED CREW AT QUARTERS NO UNAUTHORIZED ABSENTEES. 1436 U.S.S ALBACORE (SS569) ASSUMES DUTIES OF SOPA.

James L Flaherty
ET2(SS) USN

APPROVED: Kevin Hanlon LT U.S.N. COMMANDING

EXAMINED: ____________ U.S.N. NAVIGATOR.

(SIGNATURE REQUIRED ONLY WHEN NAVIGATOR IS OTHER THAN COMMANDING OFFICER.)

Digital Surrogate of NARA Original Record - NND 927605

USS X-1 (SSX-1) ZONE DESCRIPTION +4 DATE Saturday (Day) 16 (Date) June (Month), 1956

AT/PASSAGE FROM U.S. Naval Shipyard TO Portsmouth N.H.

WEATHER OBSERVATIONS

ZONE TIME	WIND DIRECTION (True)	WIND FORCE (Knots)	VISIBILITY (Miles)	WEATHER (Symbols)	BAROMETER (Inches)	TEMPERATURE Dry Bulb	TEMPERATURE Wet Bulb	CLOUDS Amount (Tenths)	CLOUDS Height	CLOUDS Type	SEA WATER TEMPERATURE	WAVES DIRECTION (True)	WAVES HEIGHT (Feet)
04													
08													
12				Same as Com Nav Base									
16				Portsmouth New Hampshire									
20													
24													

POSITION	ZONE	TIME
0800		
L		BY
λ		BY
1200		
L		BY
λ		BY
2000		
L		BY
λ		BY

LEGEND: 1—CELESTIAL 2—ELECTRONIC 3—VISUAL 4—D. R.

REMARKS

0000-2400 Resting on cradles in front of building 180, Portsmouth naval ship yard Portsmouth, New Hampshire. Receiving all power from shore. S O P A is Commanding officer of the U.S.S. Albacore (SS569) 0800 Mustered crew at quarters, no unauthorized absentees

Malone S. Jones
ENC (SS) USN

APPROVED: Kevin Hanlon LT U. S. N. COMMANDING

EXAMINED: ______ U. S. N. NAVIGATOR.
(SIGNATURE REQUIRED ONLY WHEN NAVIGATOR IS OTHER THAN COMMANDING OFFICER.)

Digital Surrogate of NARA Original Record - NND 927605

USS X-1 (SSX-1) ZONE DESCRIPTION +4 DATE Sunday (Day) 17 (Date) June (Month), 1956

AT/PASSAGE FROM US NAVAL SHIPYARD, PORTSMOUTH TO NEW HAMPSHIRE

WEATHER OBSERVATIONS

ZONE TIME	WIND		VISIBILITY	WEATHER	BAROMETER	TEMPERATURE		CLOUDS			SEA WATER TEMPERATURE	WAVES	
	DIRECTION (True)	FORCE (Knots)	(Miles)	(Symbols)	(Inches)	Dry Bulb	Wet Bulb	Amount (Tenths)	Height	Type		DIRECTION (True)	HEIGHT (Feet)
04													
08			SAME AS COM NAV BASE										
12			PORTSMOUTH, NEW HAMPSHIRE.										
16													
20													
24													

POSITION	ZONE	TIME
0800		
L		BY
λ		BY
1200		
L		BY
λ		BY
2000		
L		BY
λ		BY

LEGEND: 1—CELESTIAL 2—ELECTRONIC 3—VISUAL 4—D. R.

REMARKS

0000-2400 Resting on cradles in front of building 180, Portsmouth Naval Shipyard, Portsmouth New Hampshire. Recieving all power from shore. SOPA is Commanding Officer USS Albacore (SS 569) 0900 Mustered crew at quarters, no unauthorized absentees.

Charles W. Annable
EN2(SS) USN

APPROVED: Kevin Hanlon LT U. S. N. COMMANDING

EXAMINED: ______ U. S. N. NAVIGATOR.
(SIGNATURE REQUIRED ONLY WHEN NAVIGATOR IS OTHER THAN COMMANDING OFFICER.)

348603 O - 55 - 3

Digital Surrogate of NARA Original Record - NND 927605

Rot

USS X-1 (SSX-1) ZONE DESCRIPTION +4 DATE Monday (Day) 18 (Date) June (Month), 19 56

AT/PASSAGE FROM U.S. Naval Shipyard, Portsmouth, N.H. TO

WEATHER OBSERVATIONS

ZONE TIME	WIND		VISIBILITY	WEATHER	BAROMETER	TEMPERATURE		CLOUDS			SEA WATER TEMPERATURE	WAVES	
	DIRECTION (True)	FORCE (Knots)	(Miles)	(Symbols)	(Inches)	Dry Bulb	Wet Bulb	Amount (Tenths)	Height	Type		DIRECTION (True)	HEIGHT (Feet)
04													
08													
12													
16													
20													
24													

Same as Com. Nav. Base Portsmouth, New Hampshire.

POSITION	ZONE	TIME
0800		
L		BY
λ		BY
1200		
L		BY
λ		BY
2000		
L		BY
λ		BY

LEGEND: 1—CELESTIAL 2—ELECTRONIC 3—VISUAL 4—D. R.

REMARKS

00-24 Resting on cradles outside building 180, U.S. Naval Shipyard, Portsmouth, New Hampshire. Receiving all power from shore. SOPA is Commanding officer, USS ~~O~~ Albacore (SS569) (AGSS) 0800 Mustered crew at quarters, no unauthorized absentees. C.O. USS Sea Robin (SS407) assumes duties of SOPA 1600 C.O. USS Piper (SS409) assumes duties of SOPA.

J. A. Roberts
Ens. USN.

APPROVED: Kevin Hanlon LT U. S. N. COMMANDING

EXAMINED: ____________ U. S. N. NAVIGATOR.
(SIGNATURE REQUIRED ONLY WHEN NAVIGATOR IS OTHER THAN COMMANDING OFFICER.)

348603 O - 55 - 3

Digital Surrogate of NARA Original Record - NND 927605

USS X-1 (SS X-1) ZONE DESCRIPTION +4 DATE Tuesday 19 June, 1956
(Day) (Date) (Month)

AT/PASSAGE FROM U.S. Naval Shipyard Portsmouth TO New Hampshire

WEATHER OBSERVATIONS

ZONE TIME	WIND DIRECTION (True)	WIND FORCE (Knots)	VISIBILITY (Miles)	WEATHER (Symbols)	BAROMETER (Inches)	TEMPERATURE Dry Bulb	TEMPERATURE Wet Bulb	CLOUDS Amount (Tenths)	CLOUDS Height	CLOUDS Type	SEA WATER TEMPERATURE	WAVES DIRECTION (True)	WAVES HEIGHT (Feet)
04													
08													
12			Same as Sub Base										
16			Portsmouth, New Hampshire										
20													
24													

POSITION	ZONE	TIME
0800		
L		BY
λ		BY
1200		
L		BY
λ		BY
2000		
L		BY
λ		BY

LEGEND: 1—CELESTIAL 2—ELECTRONIC 3—VISUAL 4—D. R.

REMARKS

0000-2400 - Resting as cradle in front of building 180 Portsmouth Naval Shipyard Portsmouth New Hampshire. Receiving all power from shore. SOPA is Commanding Officer of U.S.S. Albacore (SS569)
0800 Mustered crew at quarters, no unauthorized absentees.

Malone S. Jones
ENC (SS) USN

APPROVED:
Kevin Hanlon U.S.N. COMMANDING
LT

EXAMINED:
________ U.S.N. NAVIGATOR.
(SIGNATURE REQUIRED ONLY WHEN NAVIGATOR IS OTHER THAN COMMANDING OFFICER.)

Digital Surrogate of NARA Original Record - NND 927605

USS X-1 (SS X-1) ZONE DESCRIPTION +4 DATE Wednesday 20 June, 1956
(Day) (Date) (Month)

AT/~~PASSAGE FROM~~ U.S. Naval Shipyard ~~TO~~ Portsmouth New Hampshire

WEATHER OBSERVATIONS

ZONE TIME	WIND DIRECTION (True)	WIND FORCE (Knots)	VISIBILITY (Miles)	WEATHER (Symbols)	BAROMETER (Inches)	TEMPERATURE Dry Bulb	TEMPERATURE Wet Bulb	CLOUDS Amount (Tenths)	CLOUDS Height	CLOUDS Type	SEA WATER TEMPERATURE	WAVES DIRECTION (True)	WAVES HEIGHT (Feet)
04													
08													
12	Same as ~~SOPA~~ P.S.T Com Nav Base Portsmouth, New Hampshire												
16													
20													
24													

POSITION	ZONE	TIME
0800		
L		BY
λ		BY
1200		
L		BY
λ		BY
2000		
L		BY
λ		BY

LEGEND: 1—CELESTIAL 2—ELECTRONIC 3—VISUAL 4—D. R.

REMARKS

0000-2400 Resting on cradles in front of building 180, at U.S. Naval Shipyard, Portsmouth New Hampshire. Receiving all power from Shore. SOPA is Commanding Officer USS Piper (SS409). 0800 mustered crew at quarters, no unauthorized personnel absent.

Phillip S Thompson
EN1 (SS) U.SN

APPROVED: Kevin Hanlon LT U. S. N. COMMANDING

EXAMINED: ______ U. S. N. NAVIGATOR.
(SIGNATURE REQUIRED ONLY WHEN NAVIGATOR IS OTHER THAN COMMANDING OFFICER.)

Digital Surrogate of NARA Original Record - NND 927605

USS X-1 (SSX-1) ZONE DESCRIPTION +4 DATE THURSDAY (Day) 21 (Date) JUNE (Month), 1956

AT/PASSAGE FROM US NAVAL SHIPYARD, PORTSMOUTH NEW HAMPSHIRE

WEATHER OBSERVATIONS

ZONE TIME	WIND		VISIBILITY	WEATHER	BAROMETER	TEMPERATURE		CLOUDS			SEA WATER TEMPERATURE	WAVES	
	DIRECTION (True)	FORCE (Knots)	(Miles)	(Symbols)	(Inches)	Dry Bulb	Wet Bulb	Amount (Tenths)	Height	Type		DIRECTION (True)	HEIGHT (Feet)
04													
08													
12	SAME AS COM NAV BASE												
16	PORTSMOUTH, NEW HAMPSHIRE												
20													
24													

POSITION	ZONE	TIME
0800		
L		BY
λ		BY
1200		
L		BY
λ		BY
2000		
L		BY
λ		BY

LEGEND: 1—CELESTIAL 2—ELECTRONIC 3—VISUAL 4—D. R.

REMARKS

0000-2400 Resting on cradles in front of building 180 at US Naval Shipyard, Portsmouth, New Hampshire. Recieving all power from shore. SOPA is Commanding Officer USS Piper (SS409) 0800 Mustered crew at quarters, no unauthorized absentees.

Charles W. Annable
EN2(SS) USN.

APPROVED: Kevin Hanlon LT U. S. N. COMMANDING

EXAMINED: ______ U. S. N. NAVIGATOR.
(SIGNATURE REQUIRED ONLY WHEN NAVIGATOR IS OTHER THAN COMMANDING OFFICER.)

Digital Surrogate of NARA Original Record - NND 927605

USS X-1 (SSX-1) ZONE DESCRIPTION +4 DATE Friday (Day) 22 (Date) June (Month), 19 56

AT/PASSAGE FROM US Naval Shipyard, Portsmouth TO New Hampshire.

WEATHER OBSERVATIONS

ZONE TIME	WIND		VISIBILITY	WEATHER	BAROMETER	TEMPERATURE		CLOUDS			SEA WATER TEMPERATURE	WAVES	
	DIRECTION (True)	FORCE (Knots)	(Miles)	(Symbols)	(Inches)	Dry Bulb	Wet Bulb	Amount (Tenths)	Height	Type		DIRECTION (True)	HEIGHT (Feet)
04													
08													
12					SAME AS COMNAVBASE								
16					PORTSMOUTH, NEW HAMPSHIRE								
20													
24													

POSITION	ZONE	TIME
0800		
L		BY
λ		BY
1200		
L		BY
λ		BY
2000		
L		BY
λ		BY

LEGEND: 1—CELESTIAL 2—ELECTRONIC 3—VISUAL 4—D. R.

REMARKS

0000-2400 Resting on cradles in front of building 180 at US Naval Shipyard, Portsmouth New Hampshire. Recieving all power from shore. SOPA is Commanding Officer USS Piper (SS 409). 0800 Mustered crew at quarters, no unauthorized absentees. *

Charles W. Annalle
EN2(SS) USN

* 1400 Commanding Officer of the USS Albacore (SS569) assumed duties of SOPA

APPROVED: Kevin Hanlon LT U. S. N. COMMANDING

EXAMINED: ____ U. S. N. NAVIGATOR.
(SIGNATURE REQUIRED ONLY WHEN NAVIGATOR IS OTHER THAN COMMANDING OFFICER.)

Digital Surrogate of NARA Original Record - NND 927605

USS X-1 (SSX-1) ZONE DESCRIPTION +4 DATE Saturday (Day) 23 (Date) June (Month), 1956

AT/~~PASSAGE~~ FROM U.S. Naval Shipyard, ~~TO~~ Portsmouth New Hampshire

WEATHER OBSERVATIONS

ZONE TIME	WIND		VISIBILITY	WEATHER	BAROMETER	TEMPERATURE		CLOUDS			SEA WATER TEMPERATURE	WAVES	
	DIRECTION (True)	FORCE (Knots)	(Miles)	(Symbols)	(Inches)	Dry Bulb	Wet Bulb	Amount (Tenths)	Height	Type	°	DIRECTION (True)	HEIGHT (Feet)
04													
08													
12	Same as Commanbare												
16	Portsmouth New Hampshire												
20													
24													

POSITION	ZONE	TIME
0800		
L		BY
λ		BY
1200		
L		BY
λ		BY
2000		
L		BY
λ		BY

LEGEND: 1—CELESTIAL 2—ELECTRONIC 3—VISUAL 4—D. R.

REMARKS

0000-2400 Resting on cradles in front of building 180 at U.S. Naval Shipyard, Portsmouth New Hampshire. Receiving all power from shore. SOPA is Commanding Officer U.S.S Albacore (SS569) 0800 Mustered crew at quarters, no unauthorized absentees

Phillips S Thompson
EN1 (SS) USN

APPROVED: Kevin Hanlon U. S. N. COMMANDING
LT

EXAMINED: ______ U. S. N. NAVIGATOR.
(SIGNATURE REQUIRED ONLY WHEN NAVIGATOR IS OTHER THAN COMMANDING OFFICER.)

Digital Surrogate of NARA Original Record - NND 927605

USS X-1 (SSX-1) ZONE DESCRIPTION +4 DATE SUNDAY (Day) 24 (Date) JUNE (Month), 1951

AT/PASSAGE FROM US NAVAL SHIPYARD, PORTSMOUTH, TO NEW HAMPSHIRE

WEATHER OBSERVATIONS

ZONE TIME	WIND		VISIBILITY	WEATHER	BAROMETER	TEMPERATURE		CLOUDS			SEA WATER TEMPERATURE	WAVES	
	DIRECTION (True)	FORCE (Knots)	(Miles)	(Symbols)	(Inches)	Dry Bulb	Wet Bulb	Amount (Tenths)	Height	Type		DIRECTION (True)	HEIGHT (Feet)
04													
08													
12				SAME AS COMNAVBASE									
16				PORTSMOUTH, NEW HAMPSHIRE									
20													
24													

POSITION	ZONE	TIME
0800		
L		BY
λ		BY
1200		
L		BY
λ		BY
2000		
L		BY
λ		BY

LEGEND: 1—CELESTIAL 2—ELECTRONIC 3—VISUAL 4—D. R.

REMARKS

00-24 Resting on cradles in front of building 180 at US Naval Shipyard, Portsmouth, New Hampshire. Recieving all power from shore. SOPA is Commanding Officer USS Albacore (SS569). 0800 Mustered crew at quarters, no unauthorized absentees.

Charles W. Anniak
EN2(SS) USN.

APPROVED: Kevin Hanlon LT U. S. N. COMMANDING

EXAMINED: ______ U. S. N. NAVIGATOR.

(SIGNATURE REQUIRED ONLY WHEN NAVIGATOR IS OTHER THAN COMMANDING OFFICER.)

Digital Surrogate of NARA Original Record - NND 927605

USS X-1 (SSX-1) ZONE DESCRIPTION +4 DATE Monday (Day) 25 (Date) June (Month), 1956

AT/PASSAGE FROM US Naval Shipyard TO Portsmouth New Hampshire

WEATHER OBSERVATIONS

ZONE TIME	WIND		VISIBILITY	WEATHER	BAROMETER	TEMPERATURE		CLOUDS			SEA WATER TEMPERATURE	WAVES	
	DIRECTION (True)	FORCE (Knots)	(Miles)	(Symbols)	(Inches)	Dry Bulb	Wet Bulb	Amount (Tenths)	Height	Type		DIRECTION (True)	HEIGHT (Feet)
04													
08	Same as Com. Nav. Base												
12	Portsmouth, New Hampshire												
16													
20													
24													

POSITION	ZONE	TIME
0800		
L		BY
λ		BY
1200		
L		BY
λ		BY
2000		
L		BY
λ		BY

LEGEND: 1—CELESTIAL 2—ELECTRONIC 3—VISUAL 4—D. R.

REMARKS

00-24 Resting on cradles in front of building 180 at U.S. Naval Shipyard, Portsmouth New Hampshire. Recieving all power from shore. S.O.P.A. is officer USS Albacore (SS569)*. 0800 Mustered crew at quarters, no unauthorized absentees.

Harry D. Brown
ENISS USN

* 0930 Commanding officer USS Sea Robin SS 407 assumed duties of S.O.P.A.

APPROVED: Kevin Hanlon U. S. N. COMMANDING
LT

EXAMINED: ______ U. S. N. NAVIGATOR.
(SIGNATURE REQUIRED ONLY WHEN NAVIGATOR IS OTHER THAN COMMANDING OFFICER.)

Digital Surrogate of NARA Original Record - NND 927605

USS X-1 (SS X-1) ZONE DESCRIPTION +4 DATE Tuesday (Day) 26 (Date) June (Month), 1956

AT/PASSAGE FROM U. S. Naval Shipyard TO Portsmouth New Hampshire

WEATHER OBSERVATIONS

ZONE TIME	WIND DIRECTION (True)	WIND FORCE (Knots)	VISIBILITY (Miles)	WEATHER (Symbols)	BAROMETER (Inches)	TEMPERATURE Dry Bulb	TEMPERATURE Wet Bulb	CLOUDS Amount (Tenths)	CLOUDS Height	CLOUDS Type	SEA WATER TEMPERATURE	WAVES DIRECTION (True)	WAVES HEIGHT (Feet)
04													
08													
12	Same as Commanbase												
16	Portsmouth New Hampshire												
20													
24													

POSITION	ZONE	TIME
0800		
L	BY	
λ	BY	
1200		
L	BY	
λ	BY	
2000		
L	BY	
λ	BY	

LEGEND: 1—CELESTIAL 2—ELECTRONIC 3—VISUAL 4—D. R.

REMARKS

0000-2400 Resting on cradles in front of building 180 at U.S. Naval Shipyard, Portsmouth New Hampshire. Receiving all power from shore. SOPA is Commanding Officer U.S.S Sea Robin (SS 407) 0800 Mustered crew at quarters, no unauthorized absentees

Phillip S Thompson

EN1 (SS) U.S.N

APPROVED: Kevin Hanlon U. S. N. COMMANDING
LT

EXAMINED: ______ U. S. N. NAVIGATOR.
(SIGNATURE REQUIRED ONLY WHEN NAVIGATOR IS OTHER THAN COMMANDING OFFICER.)

Digital Surrogate of NARA Original Record - NND 927605

USS X-1 (SSX-1) ZONE DESCRIPTION +4 DATE Wednesday 27 June, 1956
(Day) (Date) (Month)

AT/PASSAGE FROM US Naval Shipyard, Portsmouth, New Hampshire.

WEATHER OBSERVATIONS

ZONE TIME	WIND DIRECTION (True)	WIND FORCE (Knots)	VISIBILITY (Miles)	WEATHER (Symbols)	BAROMETER (Inches)	TEMPERATURE Dry Bulb	TEMPERATURE Wet Bulb	CLOUDS Amount (Tenths)	CLOUDS Height	CLOUDS Type	SEA WATER TEMPERATURE	WAVES DIRECTION (True)	WAVES HEIGHT (Feet)
04													
08													
12			Same As Com. Nav. Base										
16													
20			Portsmouth, New Hampshire.										
24													

POSITION	ZONE	TIME
0800		
L		BY
λ		BY
1200		
L		BY
λ		BY
2000		
L		BY
λ		BY

LEGEND: 1—CELESTIAL 2—ELECTRONIC 3—VISUAL 4—D. R.

REMARKS

00-24 Resting on cradles outside building 180, U S Naval Shipyard, Portsmouth, New Hampshire. Receiving all power from shore. SOPA is Commanding Officer, USS Sea Robin (SS-407) 0800 Mustered Crew at quarters, No un-authorized absentees.

J. A. Roberts
EM1 USN.

APPROVED: Kevin Hanlon U. S. N. COMMANDING
LT

EXAMINED: ______ U. S. N. NAVIGATOR.
(SIGNATURE REQUIRED ONLY WHEN NAVIGATOR IS OTHER THAN COMMANDING OFFICER.)

Digital Surrogate of NARA Original Record - NND 927605

USS X-1 (SSX-1) ZONE DESCRIPTION +4 DATE THURSDAY 28 JUNE, 1956
(Day) (Date) (Month)

AT/~~PASSAGE~~ FROM U.S. NAVAL SHIPYARD PORTSMOUTH, NEW HAMPSHIRE

WEATHER OBSERVATIONS

ZONE TIME	WIND		VISIBILITY	WEATHER	BAROMETER	TEMPERATURE		CLOUDS			SEA WATER TEMPERATURE	WAVES	
	DIRECTION (True)	FORCE (Knots)	(Miles)	(Symbols)	(Inches)	Dry Bulb	Wet Bulb	Amount (Tenths)	Height	Type		DIRECTION (True)	HEIGHT (Feet)
04													
08				SAME AS COMNAVBASE									
12				PORTSMOUTH, NEW HAMPSHIRE									
16													
20													
24													

POSITION	ZONE	TIME
0800		
L		BY
λ		BY
1200		
L		BY
λ		BY
2000		
L		BY
λ		BY

LEGEND: 1—CELESTIAL 2—ELECTRONIC 3—VISUAL 4—D. R.

REMARKS

0000-2400 RESTING ON CRADLES IN FRONT OF BUILDING 180 AT U.S. NAVAL SHIPYARD, PORTSMOUTH NEW HAMPSHIRE. S.O.P.A. IS COMMANDING OFFICER U.S.S. SEA ROBIN (SS 407) RECIEVING All POWER FROM SHORE. 0800 MUSTERD CREW AT QUARTERS NO UNAUTHORIZED ABSENTEES.

James L. Flaherty
ET2(SS) USN

APPROVED: Kevin Hanlon U. S. N. COMMANDING
LT

EXAMINED: ____________ U. S. N. NAVIGATOR.
(SIGNATURE REQUIRED ONLY WHEN NAVIGATOR IS OTHER THAN COMMANDING OFFICER.)

Digital Surrogate of NARA Original Record - NND 927605

USS X-1 (SSX-1) ZONE DESCRIPTION +4 DATE FRIDAY (Day) 29 (Date) JUNE (Month), 1956

AT/PASSAGE FROM US NAVAL SHIPYARD PORTSMOUTH, NEW HAMPSHIRE.

WEATHER OBSERVATIONS

ZONE TIME	WIND DIRECTION (True)	WIND FORCE (Knots)	VISIBILITY (Miles)	WEATHER (Symbols)	BAROMETER (Inches)	TEMPERATURE Dry Bulb	TEMPERATURE Wet Bulb	CLOUDS Amount (Tenths)	CLOUDS Height	CLOUDS Type	SEA WATER TEMPERATURE	WAVES DIRECTION (True)	WAVES HEIGHT (Feet)
04													
08			SAME AS COMNAVBASE										
12			PORTSMOUTH NEW HAMPSHIRE										
16													
20													
24													

POSITION	ZONE	TIME
0800		
L		BY
λ		BY
1200		
L		BY
λ		BY
2000		
L		BY
λ		BY

LEGEND: 1—CELESTIAL 2—ELECTRONIC 3—VISUAL 4—D. R.

REMARKS

0000-2400 Resting on cradles in front of Building 180 at US Naval Shipyard, Portsmouth, New Hampshire. SOPA is Commanding Officer USS Sea Robin (SS407). Recieving all power from shore. 0800 Mustered crew at quarters, no unauthorized absentees. *

Charles W. Annable
EN2(SS) USN.

* Commanding Officer of USS Albacore assumed duties of SOPA.

APPROVED: Kevin Hanlon U. S. N. COMMANDING

4T

EXAMINED: ______ U. S. N. NAVIGATOR.
(SIGNATURE REQUIRED ONLY WHEN NAVIGATOR IS OTHER THAN COMMANDING OFFICER.)

348603 O - 55 - 3

Digital Surrogate of NARA Original Record - NND 927605

USS X-1 (SS X-1) ZONE DESCRIPTION + 4 DATE Saturday (Day) 30 (Date) June (Month), 1956

AT/PASSAGE FROM U.S. Naval Shipyard, TO Portsmouth, New Hampshire.

WEATHER OBSERVATIONS

ZONE TIME	WIND DIRECTION (True)	WIND FORCE (Knots)	VISIBILITY (Miles)	WEATHER (Symbols)	BAROMETER (Inches)	TEMPERATURE Dry Bulb	TEMPERATURE Wet Bulb	CLOUDS Amount (Tenths)	CLOUDS Height	CLOUDS Type	SEA WATER TEMPERATURE	WAVES DIRECTION (True)	WAVES HEIGHT (Feet)
04													
08			Same As Com Nav Base,										
12													
16			Portsmouth, New Hampshire.										
20													
24													

POSITION	ZONE	TIME
0800		
L		BY
λ		BY
1200		
L		BY
λ		BY
2000		
L		BY
λ		BY

LEGEND: 1—CELESTIAL 2—ELECTRONIC 3—VISUAL 4—D. R.

REMARKS

00-24 Resting on cradles in front of building 180. Receiving all power from shore. At U.S. Naval Shipyard, Portsmouth, New Hampshire. SOPA is commanding officer USS Albacore (SS-569). 0800 Mustered crew at quarters. No unauthorized absentees.

J. A. Roberts
ICM, USN.

APPROVED: Kevin Hanlon LT U. S. N. COMMANDING

EXAMINED: ______ U. S. N. NAVIGATOR.
(SIGNATURE REQUIRED ONLY WHEN NAVIGATOR IS OTHER THAN COMMANDING OFFICER.)

Digital Surrogate of NARA Original Record - NND 927605

USS ______ ZONE DESCRIPTION ______ DATE ______ (Day) (Date) (Month), 19__

AT/PASSAGE FROM ______ TO ______

WEATHER OBSERVATIONS

ZONE TIME	WIND		VISIBILITY	WEATHER	BAROMETER	TEMPERATURE		CLOUDS			SEA WATER TEMPERATURE	WAVES	
	DIRECTION (True)	FORCE (Knots)	(Miles)	(Symbols)	(Inches)	Dry Bulb	Wet Bulb	Amount (Tenths)	Height	Type		DIRECTION (True)	HEIGHT (Feet)
04													
08													
12													
16													
20													
24													

POSITION	ZONE	TIME
0800		
L ______	BY ______	
λ ______	BY ______	
1200		
L ______	BY ______	
λ ______	BY ______	
2000		
L ______	BY ______	
λ ______	BY ______	

LEGEND: 1—CELESTIAL 2—ELECTRONIC 3—VISUAL 4—D. R.

REMARKS

APPROVED:

______ U. S. N. COMMANDING

EXAMINED:

______ U. S. N. NAVIGATOR.

(SIGNATURE REQUIRED ONLY WHEN NAVIGATOR IS OTHER THAN COMMANDING OFFICER.)

Digital Surrogate of NARA Original Record - NND 927605

USS ______ ZONE DESCRIPTION ______ DATE ______ (Day) (Date) (Month), 19__

AT/PASSAGE FROM ______ TO ______

WEATHER OBSERVATIONS

ZONE TIME	WIND		VISIBILITY	WEATHER	BAROMETER	TEMPERATURE		CLOUDS			SEA WATER TEMPERATURE	WAVES	
	DIRECTION (True)	FORCE (Knots)	(Miles)	(Symbols)	(Inches)	Dry Bulb	Wet Bulb	Amount (Tenths)	Height	Type		DIRECTION (True)	HEIGHT (Feet)
04													
08													
12													
16													
20													
24													

POSITION	ZONE	TIME
0800		
L ______	BY ______	
λ ______	BY ______	
1200		
L ______	BY ______	
λ ______	BY ______	
2000		
L ______	BY ______	
λ ______	BY ______	

LEGEND:
1—CELESTIAL
2—ELECTRONIC
3—VISUAL
4—D. R.

REMARKS

APPROVED: ______ U. S. N. COMMANDING

EXAMINED: ______ U. S. N. NAVIGATOR.
(SIGNATURE REQUIRED ONLY WHEN NAVIGATOR IS OTHER THAN COMMANDING OFFICER.)

348603 O - 55 - 3

Digital Surrogate of NARA Original Record - NND 927605

USS ______ ZONE DESCRIPTION ______ DATE ______ (Day) (Date) (Month), 19____

AT/PASSAGE FROM ______ TO ______

WEATHER OBSERVATIONS

ZONE TIME	WIND		VISIBILITY	WEATHER	BAROMETER	TEMPERATURE		CLOUDS			SEA WATER TEMPERATURE	WAVES	
	DIRECTION (True)	FORCE (Knots)	(Miles)	(Symbols)	(Inches)	Dry Bulb	Wet Bulb	Amount (Tenths)	Height	Type		DIRECTION (True)	HEIGHT (Feet)
04													
08													
12													
16													
20													
24													

POSITION	ZONE	TIME
0800		
L ______		BY ______
λ ______		BY ______
1200		
L ______		BY ______
λ ______		BY ______
2000		
L ______		BY ______
λ ______		BY ______

LEGEND: 1—CELESTIAL 2—ELECTRONIC 3—VISUAL 4—D. R.

REMARKS

APPROVED:

______ U. S. N. COMMANDING

EXAMINED:

______ U. S. N. NAVIGATOR.

(SIGNATURE REQUIRED ONLY WHEN NAVIGATOR IS OTHER THAN COMMANDING OFFICER.)

Digital Surrogate of NARA Original Record - NND 927605

USS ______ ZONE DESCRIPTION ______ DATE ______ (Day) (Date) (Month), 19____

AT/PASSAGE FROM ______ TO ______

WEATHER OBSERVATIONS

ZONE TIME	WIND		VISIBILITY	WEATHER	BAROMETER	TEMPERATURE		CLOUDS			SEA WATER TEMPERATURE	WAVES	
	DIRECTION (True)	FORCE (Knots)	(Miles)	(Symbols)	(Inches)	Dry Bulb	Wet Bulb	Amount (Tenths)	Height	Type		DIRECTION (True)	HEIGHT (Feet)
04													
08													
12													
16													
20													
24													

POSITION	ZONE	TIME
0800		
L		BY
λ		BY
1200		
L		BY
λ		BY
2000		
L		BY
λ		BY

LEGEND: 1—CELESTIAL 2—ELECTRONIC 3—VISUAL 4—D. R.

REMARKS

APPROVED: ______ U. S. N. COMMANDING

EXAMINED: ______ U. S. N. NAVIGATOR.
(SIGNATURE REQUIRED ONLY WHEN NAVIGATOR IS OTHER THAN COMMANDING OFFICER.)

Digital Surrogate of NARA Original Record - NND 927605

USS ______ ZONE DESCRIPTION ______ DATE ______ (Day) (Date) (Month), 19____

AT/PASSAGE FROM ______ TO ______

WEATHER OBSERVATIONS

ZONE TIME	WIND		VISI-BILITY	WEATH-ER	BAROM-ETER	TEMPERATURE		CLOUDS			SEA WATER TEMPER-ATURE	WAVES	
	DIRECTION (True)	FORCE (Knots)	(Miles)	(Sym-bols)	(Inches)	Dry Bulb	Wet Bulb	Amount (Tenths)	Height	Type		DIRECTION (True)	HEIGHT (Feet)
04													
08													
12													
16													
20													
24													

POSITION	ZONE	TIME
0800		
L ______		BY ______
λ ______		BY ______
1200		
L ______		BY ______
λ ______		BY ______
2000		
L ______		BY ______
λ ______		BY ______

LEGEND: 1—CELESTIAL 2—ELECTRONIC 3—VISUAL 4—D. R.

REMARKS

APPROVED: ______ U. S. N. COMMANDING

EXAMINED: ______ U. S. N. NAVIGATOR.

(SIGNATURE REQUIRED ONLY WHEN NAVIGATOR IS OTHER THAN COMMANDING OFFICER.)

Digital Surrogate of NARA Original Record - NND 927605

USS ______ ZONE DESCRIPTION ______ DATE ______ (Day) (Date) (Month), 19____

AT/PASSAGE FROM ______ TO ______

WEATHER OBSERVATIONS

ZONE TIME	WIND		VISIBILITY	WEATHER	BAROMETER	TEMPERATURE		CLOUDS			SEA WATER TEMPERATURE	WAVES	
	DIRECTION (True)	FORCE (Knots)	(Miles)	(Symbols)	(Inches)	Dry Bulb	Wet Bulb	Amount (Tenths)	Height	Type		DIRECTION (True)	HEIGHT (Feet)
04													
08													
12													
16													
20													
24													

POSITION	ZONE	TIME
0800		
L ______		BY ______
λ ______		BY ______
1200		
L ______		BY ______
λ ______		BY ______
2000		
L ______		BY ______
λ ______		BY ______

LEGEND: 1—CELESTIAL 2—ELECTRONIC 3—VISUAL 4—D. R.

REMARKS

APPROVED: EXAMINED:

______ U. S. N. COMMANDING ______ U. S. N. NAVIGATOR.

(SIGNATURE REQUIRED ONLY WHEN NAVIGATOR IS OTHER THAN COMMANDING OFFICER.)

348603 O - 55 - 3

Digital Surrogate of NARA Original Record - NND 927605

USS ______ ZONE DESCRIPTION ______ DATE ______ (Day) (Date) (Month), 19__

AT/PASSAGE FROM ______ TO ______

WEATHER OBSERVATIONS

ZONE TIME	WIND		VISIBILITY	WEATHER	BAROMETER	TEMPERATURE		CLOUDS			SEA WATER TEMPERATURE	WAVES	
	DIRECTION (True)	FORCE (Knots)	(Miles)	(Symbols)	(Inches)	Dry Bulb	Wet Bulb	Amount (Tenths)	Height	Type		DIRECTION (True)	HEIGHT (Feet)
04													
08													
12													
16													
20													
24													

POSITION	ZONE	TIME
0800		
L ______	BY ______	
λ ______	BY ______	
1200		
L ______	BY ______	
λ ______	BY ______	
2000		
L ______	BY ______	
λ ______	BY ______	

LEGEND: 1—CELESTIAL 2—ELECTRONIC 3—VISUAL 4—D. R.

REMARKS

APPROVED:

______ U. S. N. COMMANDING

EXAMINED:

______ U. S. N. NAVIGATOR.

(SIGNATURE REQUIRED ONLY WHEN NAVIGATOR IS OTHER THAN COMMANDING OFFICER.)

348603 O - 55 - 3

Digital Surrogate of NARA Original Record - NND 927605

USS ______ ZONE DESCRIPTION ______ DATE ______ (Day) (Date) (Month), 19____

AT/PASSAGE FROM ______ TO ______

WEATHER OBSERVATIONS

ZONE TIME	WIND		VISIBILITY	WEATHER	BAROMETER	TEMPERATURE		CLOUDS			SEA WATER TEMPERATURE	WAVES	
	DIRECTION (True)	FORCE (Knots)	(Miles)	(Symbols)	(Inches)	Dry Bulb	Wet Bulb	Amount (Tenths)	Height	Type		DIRECTION (True)	HEIGHT (Feet)
04													
08													
12													
16													
20													
24													

POSITION	ZONE	TIME
0800		
L ______	BY ______	
λ ______	BY ______	
1200		
L ______	BY ______	
λ ______	BY ______	
2000		
L ______	BY ______	
λ ______	BY ______	

LEGEND:
1—CELESTIAL
2—ELECTRONIC
3—VISUAL
4—D. R.

REMARKS

APPROVED: **EXAMINED:**

______ U. S. N. COMMANDING ______ U. S. N. NAVIGATOR.

(SIGNATURE REQUIRED ONLY WHEN NAVIGATOR IS OTHER THAN COMMANDING OFFICER.)

348603 O - 55 - 3

Digital Surrogate of NARA Original Record - NND 927605

USS ______ ZONE DESCRIPTION ______ DATE ______ (Day) (Date) (Month), 19____

AT/PASSAGE FROM ______ TO ______

WEATHER OBSERVATIONS

ZONE TIME	WIND		VISI-BILITY	WEATH-ER	BAROM-ETER	TEMPERATURE		CLOUDS			SEA WATER TEMPER-ATURE	WAVES	
	DIRECTION (True)	FORCE (Knots)	(Miles)	(Sym-bols)	(Inches)	Dry Bulb	Wet Bulb	Amount (Tenths)	Height	Type		DIRECTION (True)	HEIGHT (Feet)
04													
08													
12													
16													
20													
24													

POSITION	ZONE	TIME
0800		
L ____		BY ____
λ ____		BY ____
1200		
L ____		BY ____
λ ____		BY ____
2000		
L ____		BY ____
λ ____		BY ____

LEGEND: 1—CELESTIAL 2—ELECTRONIC 3—VISUAL 4—D. R.

REMARKS

APPROVED: ______ U. S. N. COMMANDING

EXAMINED: ______ U. S. N. NAVIGATOR.

(SIGNATURE REQUIRED ONLY WHEN NAVIGATOR IS OTHER THAN COMMANDING OFFICER.)

348603 O - 55 - 3

Digital Surrogate of NARA Original Record - NND 927605

USS ______ ZONE DESCRIPTION ______ DATE ______ (Day) (Date) (Month), 19____

AT/PASSAGE FROM ______ TO ______

WEATHER OBSERVATIONS

ZONE TIME	WIND		VISIBILITY	WEATHER	BAROMETER	TEMPERATURE		CLOUDS			SEA WATER TEMPERATURE	WAVES	
	DIRECTION (True)	FORCE (Knots)	(Miles)	(Symbols)	(Inches)	Dry Bulb	Wet Bulb	Amount (Tenths)	Height	Type		DIRECTION (True)	HEIGHT (Feet)
04													
08													
12													
16													
20													
24													

POSITION	ZONE	TIME
0800		
L ______	BY ______	
λ ______	BY ______	
1200		
L ______	BY ______	
λ ______	BY ______	
2000		
L ______	BY ______	
λ ______	BY ______	

LEGEND: 1—CELESTIAL 2—ELECTRONIC 3—VISUAL 4—D. R.

REMARKS

APPROVED:

______ U. S. N. COMMANDING

EXAMINED:

______ U. S. N. NAVIGATOR.
(SIGNATURE REQUIRED ONLY WHEN NAVIGATOR IS OTHER THAN COMMANDING OFFICER.)

Digital Surrogate of NARA Original Record - NND 927605

USS ______ ZONE DESCRIPTION ______ DATE ______ (Day) ______ (Date) ______ (Month) ______, 19____

AT/PASSAGE FROM ______ TO ______

WEATHER OBSERVATIONS

ZONE TIME	WIND		VISIBILITY	WEATHER	BAROMETER	TEMPERATURE		CLOUDS			SEA WATER TEMPERATURE	WAVES	
	DIRECTION (True)	FORCE (Knots)	(Miles)	(Symbols)	(Inches)	Dry Bulb	Wet Bulb	Amount (Tenths)	Height	Type		DIRECTION (True)	HEIGHT (Feet)
04													
08													
12													
16													
20													
24													

POSITION	ZONE	TIME
0800		
L ______		BY ______
λ ______		BY ______
1200		
L ______		BY ______
λ ______		BY ______
2000		
L ______		BY ______
λ ______		BY ______

LEGEND: 1—CELESTIAL 2—ELECTRONIC 3—VISUAL 4—D. R.

REMARKS

APPROVED: ______ U. S. N. COMMANDING

EXAMINED: ______ U. S. N. NAVIGATOR.

(SIGNATURE REQUIRED ONLY WHEN NAVIGATOR IS OTHER THAN COMMANDING OFFICER.)

348603 O - 55 - 3

Digital Surrogate of NARA Original Record - NND 927605

USS ______________ ZONE DESCRIPTION ________ DATE ______________ (Day) (Date) (Month), 19____

AT/PASSAGE FROM ______________ TO ______________

WEATHER OBSERVATIONS

ZONE TIME	WIND		VISIBILITY	WEATHER	BAROMETER	TEMPERATURE		CLOUDS			SEA WATER TEMPERATURE	WAVES	
	DIRECTION (True)	FORCE (Knots)	(Miles)	(Symbols)	(Inches)	Dry Bulb	Wet Bulb	Amount (Tenths)	Height	Type		DIRECTION (True)	HEIGHT (Feet)
04													
08													
12													
16													
20													
24													

POSITION	ZONE	TIME
0800		
L ______	BY ______	
λ ______	BY ______	
1200		
L ______	BY ______	
λ ______	BY ______	
2000		
L ______	BY ______	
λ ______	BY ______	

LEGEND: 1—CELESTIAL
2—ELECTRONIC
3—VISUAL
4—D. R.

REMARKS

APPROVED: **EXAMINED:**

______________ **U. S. N. COMMANDING** ______________ **U. S. N. NAVIGATOR.**

(SIGNATURE REQUIRED ONLY WHEN NAVIGATOR IS OTHER THAN COMMANDING OFFICER.)

Digital Surrogate of NARA Original Record - NND 927605

USS ________ ZONE DESCRIPTION ________ DATE ________ (Day) (Date) (Month), 19____

AT/PASSAGE FROM ________ TO ________

WEATHER OBSERVATIONS

ZONE TIME	WIND		VISIBILITY	WEATHER	BAROMETER	TEMPERATURE		CLOUDS			SEA WATER TEMPERATURE	WAVES	
	DIRECTION (True)	FORCE (Knots)	(Miles)	(Symbols)	(Inches)	Dry Bulb	Wet Bulb	Amount (Tenths)	Height	Type		DIRECTION (True)	HEIGHT (Feet)
04													
08													
12													
16													
20													
24													

POSITION	ZONE	TIME
0800		
L ________	BY ________	
λ ________	BY ________	
1200		
L ________	BY ________	
λ ________	BY ________	
2000		
L ________	BY ________	
λ ________	BY ________	

LEGEND: 1—CELESTIAL 2—ELECTRONIC 3—VISUAL 4—D. R.

REMARKS

APPROVED: EXAMINED:

________ U. S. N. COMMANDING ________ U. S. N. NAVIGATOR.

(SIGNATURE REQUIRED ONLY WHEN NAVIGATOR IS OTHER THAN COMMANDING OFFICER.)

348603 O - 55 - 3

Digital Surrogate of NARA Original Record - NND 927605

USS ______ ZONE DESCRIPTION ______ DATE ______ (Day) (Date) (Month) , 19____

AT/PASSAGE FROM ______ TO ______

WEATHER OBSERVATIONS

ZONE TIME	WIND		VISI-BILITY	WEATH-ER	BAROM-ETER	TEMPERATURE		CLOUDS			SEA WATER TEMPER-ATURE	WAVES	
	DIRECTION (True)	FORCE (Knots)	(Miles)	(Sym-bols)	(Inches)	Dry Bulb	Wet Bulb	Amount (Tenths)	Height	Type		DIRECTION (True)	HEIGHT (Feet)
04													
08													
12													
16													
20													
24													

POSITION	ZONE	TIME
0800		
L ______		BY ______
λ ______		BY ______
1200		
L ______		BY ______
λ ______		BY ______
2000		
L ______		BY ______
λ ______		BY ______

LEGEND: 1—CELESTIAL
2—ELECTRONIC
3—VISUAL
4—D. R.

REMARKS

APPROVED: EXAMINED:

______ U. S. N. COMMANDING ______ U. S. N. NAVIGATOR.

(SIGNATURE REQUIRED ONLY WHEN NAVIGATOR IS OTHER THAN COMMANDING OFFICER.)

348603 O - 55 - 3

Digital Surrogate of NARA Original Record - NND 927605

USS ______ ZONE DESCRIPTION ______ DATE ______ (Day) (Date) (Month) , 19____

AT/PASSAGE FROM ______ TO ______

WEATHER OBSERVATIONS

ZONE TIME	WIND		VISIBILITY	WEATHER	BAROMETER	TEMPERATURE		CLOUDS			SEA WATER TEMPERATURE	WAVES	
	DIRECTION (True)	FORCE (Knots)	(Miles)	(Symbols)	(Inches)	Dry Bulb	Wet Bulb	Amount (Tenths)	Height	Type		DIRECTION (True)	HEIGHT (Feet)
04													
08													
12													
16													
20													
24													

POSITION	ZONE	TIME
0800		
L ______		BY ______
λ ______		BY ______
1200		
L ______		BY ______
λ ______		BY ______
2000		
L ______		BY ______
λ ______		BY ______

LEGEND: 1—CELESTIAL
2—ELECTRONIC
3—VISUAL
4—D. R.

REMARKS

APPROVED:

______ **U. S. N. COMMANDING**

EXAMINED:

______ **U. S. N. NAVIGATOR.**

(SIGNATURE REQUIRED ONLY WHEN NAVIGATOR IS OTHER THAN COMMANDING OFFICER.)

348603 O - 55 - 3

Digital Surrogate of NARA Original Record - NND 927605

USS ______ ZONE DESCRIPTION ______ DATE ______ (Day) (Date) (Month), 19____

AT/PASSAGE FROM ______ TO ______

WEATHER OBSERVATIONS

ZONE TIME	WIND		VISI-BILITY	WEATH-ER	BAROM-ETER	TEMPERATURE		CLOUDS			SEA WATER TEMPER-ATURE	WAVES	
	DIRECTION (True)	FORCE (Knots)	(Miles)	(Sym-bols)	(Inches)	Dry Bulb	Wet Bulb	Amount (Tenths)	Height	Type		DIRECTION (True)	HEIGHT (Feet)
04													
08													
12													
16													
20													
24													

POSITION	ZONE	TIME
0800		
L ______		BY ______
λ ______		BY ______
1200		
L ______		BY ______
λ ______		BY ______
2000		
L ______		BY ______
λ ______		BY ______

LEGEND:
1—CELESTIAL
2—ELECTRONIC
3—VISUAL
4—D. R.

REMARKS

APPROVED:

______ U. S. N. COMMANDING

EXAMINED:

______ U. S. N. NAVIGATOR.

(SIGNATURE REQUIRED ONLY WHEN NAVIGATOR IS OTHER THAN COMMANDING OFFICER.)

348603 O - 55 - 3

Digital Surrogate of NARA Original Record - NND 927605

USS ______ ZONE DESCRIPTION ______ DATE ______ (Day) (Date) (Month), 19____

AT/PASSAGE FROM ______ TO ______

WEATHER OBSERVATIONS

ZONE TIME	WIND		VISI-BILITY	WEATH-ER	BAROM-ETER	TEMPERATURE		CLOUDS			SEA WATER TEMPER-ATURE	WAVES	
	DIRECTION (True)	FORCE (Knots)	(Miles)	(Symbols)	(Inches)	Dry Bulb	Wet Bulb	Amount (Tenths)	Height	Type		DIRECTION (True)	HEIGHT (Feet)
04													
08													
12													
16													
20													
24													

POSITION	ZONE	TIME
0800		
L ______		BY ______
λ ______		BY ______
1200		
L ______		BY ______
λ ______		BY ______
2000		
L ______		BY ______
λ ______		BY ______

LEGEND: 1—CELESTIAL 2—ELECTRONIC 3—VISUAL 4—D. R.

REMARKS

APPROVED:

______ U. S. N. COMMANDING

EXAMINED:

______ U. S. N. NAVIGATOR.

(SIGNATURE REQUIRED ONLY WHEN NAVIGATOR IS OTHER THAN COMMANDING OFFICER.)

348603 O - 55 - 3

Digital Surrogate of NARA Original Record - NND 927605

USS ______ ZONE DESCRIPTION ______ DATE ______ (Day) (Date) (Month), 19____

AT/PASSAGE FROM ______ TO ______

WEATHER OBSERVATIONS

ZONE TIME	WIND		VISIBILITY	WEATHER	BAROMETER	TEMPERATURE		CLOUDS			SEA WATER TEMPERATURE	WAVES	
	DIRECTION (True)	FORCE (Knots)	(Miles)	(Symbols)	(Inches)	Dry Bulb	Wet Bulb	Amount (Tenths)	Height	Type		DIRECTION (True)	HEIGHT (Feet)
04													
08													
12													
16													
20													
24													

POSITION	ZONE	TIME
0800		
L ______		BY ______
λ ______		BY ______
1200		
L ______		BY ______
λ ______		BY ______
2000		
L ______		BY ______
λ ______		BY ______

LEGEND: 1—CELESTIAL
2—ELECTRONIC
3—VISUAL
4—D. R.

REMARKS

APPROVED:

______ U. S. N. COMMANDING

EXAMINED:

______ U. S. N. NAVIGATOR.
(SIGNATURE REQUIRED ONLY WHEN NAVIGATOR IS OTHER THAN COMMANDING OFFICER.)

348603 O - 55 - 3